

- Large, clear backlit LCD display
- Zero, tare and accumulation
- Weight accumulation and memory
- Check-weighing with alarm
- Counting function
- Adjustable vibration filtering
- 4Ah battery 6V Rechargeable
- Overload protection up to %125
- printing function / 232-RS
- Response time **3-5 seconds**

